

FIELD INSPECTION REPORT

Date of Inspection : 23-12-2020		District: East Champaran	
Division : Pakhridya		Length (km): 1.378	
Name of the Road: Lohar Tola to Chauhania Yadav Tola			
Scheme/Programme:		MAINTENANCE MMSY	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance ☒	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/AJ
b)	Condition of Surfacing	S/U ☒
c)	Riding Quality	S/U
d)	Road Camber	S/AJ
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

W
23.12.2020
(Signature)

NAME: Dharmendra Kumar

DESIGNATION: JE