

FIELD INSPECTION REPORT

Date of Inspection : 23.12.2020		District: East-champaran	
Division : Pakhridyal		Length (km): 0.850	
Name of the Road: Koriya Kajraha Nonia Toli to Madhuban sheohar Road			
Scheme/Programme: MAINTENANCE		Road Id No.: 67TSNY	
Package No.:		Ongoing/Completed/Under Maintenance ☒	
Status of the Project:		New Connectivity/Up gradation/ Maintenance	
Work is a case of:			
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		SAU
a)	Road Junction condition		SAU
b)	Condition of Surfacing		SAU
c)	Riding Quality		SAU
d)	Road Camber		SAU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		NA

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

W
23.12.2020
(Signature)

NAME: Dharmendra Kumar

DESIGNATION: JE