

INSPECTION REPORT		
Date of Inspection : 23.12.2020		District: East Champaran
Division : Pakriddha		Length (km): 1.10
Name of the Road: Madhuban Laigash Road to Koriya Khap middle sch		
Scheme/Programme: MAINTENANCE		UTSNY
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance ☒		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SAI
b)	Condition of Surfacing	SAI
c)	Riding Quality	SAI
d)	Road Camber	SAI
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

W
23.12.2020
(Signature)

NAME: Dharmendra Kumar

DESIGNATION: JIE