

FIELD INSPECTION REPORT

Date of Inspection : 15.11.20		District: Samastipur	
Division : Samastipur		Length (km):	
Name of the Road: L044 Trimbani To Ram Tola			
Scheme/Programme: MAINTENANCE			
Package No.: M.M.C.S.V(Se)		Road Id No.:	
Status of the Project: Ongoing/Completed/Under-Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			

Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	✓U
b)	Condition of Surfacing	✓U
c)	Riding Quality	✓U
d)	Road Camber	✓U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Some free
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓cs/No
4	Compliance History	
a)	Status of ATR's & any others	Not

Overall Rating :	Satisfactory (S)
	Satisfactory but requires Improvement (SRI)
	Unsatisfactory (U)

(Signature) 11/

NAME: