


FIELD INSPECTION REPORT

Date of Inspection: 21.12.2020		District: Samastipur	
Division: RWD Dalsinghsarai		Length(km): 2.4	
Name of Road : T03 to Bisanpur			
Scheme / Programme: MAINTENANCE		mmbsy (GEM)	
Package No:		Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of:		New Connectivity/ Up gradation/ Maintenance	
Sl. No	Parameters to be Checked		Remarks
1	Pavement		
a)	Road Junction Condition	S	
b)	Condition of Surfacing	R	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S	
f)	Constraction Joint provided or not(CC Pavement)	-	
g)	Compaction of flank/slope & raincuts if any	S	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S	
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	-	
c)	Condition of railings/slab/approach for Bridge	-	
3	Road Furniture		
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	R-E	
4	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating : U

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	
✓ Unsatisfactory(U)	


 21.12.2020
 (Signature)

NAME:

DESIGNATION :

Ramesh Kumar Singh
 JE