

FIELD INSPECTION REPORT

Date of Inspection: 22-12-2020	District: Samastipur	
Division: RWD Dalsinghsarai	Length(km): 1.060 km	
Name of Road: To Sarai Panshi to Sheetal patti Jodga		
Scheme / Programme: MAINTENANCE		
Package No: MM 6254	Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/ Up gradation/ Maintenance	
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	
f)	Constriction Joint provided or not(CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	SPI
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridge	
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	N
4	Compliance History	
a)	Status of ATR's & any others	N

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SPI
Unsatisfactory(U)	

NAME-

Anil Kumar

22/12/2020
(Signature)