

FIELD INSPECTION REPORT

Date of Inspection : 25/12/20	District: Nalanda
Division : Rajgir	Length (km): 1.049 K.m.
Name of the Road: Rajgir Giniyak Path ke Rasalpur Mod To Rasalpur	
Scheme/Programme: MAINTENANCE	MMGSY (SC)
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance ☒
Work is a case of:	New Connectivity/Up gradation/ Maintenance ☒

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓/U
b)	Condition of Surfacing	✓/U
c)	Riding Quality	S/U
d)	Road Camber	✓/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/✓
g)	Compaction of flank/slope & raincuts if any	Yes/✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U (N/A)
c)	Condition of railings/slab/approach for Bridges	S/SRI/U (N/A)
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/200m & stones/Pavement road markings are provided and maintained	✓/S/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Rampresh kumar
JE
NAME: Rajgir


 25/12/20
 JE
 (Signature)