FIELD INSPECTION REPORT

		THE LINSPE	CTION REPORT		-
Date of Ir	spection :	24/12/20	District:	A hou	landla!
Division :		Pargoir.	A SESTIMATE OF THE PARTY OF THE	O.A	150 pus
Name of	the Road:	DIATERNA A	Length (km):	10	20 C
		MAINTENANCE MONC TO GOODY		Mainteneg.	
Package	No.:		Road Id No.:	1 3	
Status of the Project:		Ongoing/Complete	d/Under Maintenance	1000	
Work is a case of:		New Connectivity/Up gradation/ Maintenance		Mer	rosteria
Sl. No.		Parameters t	o be checked		Remarks
1.	Pavement			4	The state of the s
a)	Road Junction condition S/U_/				
b)	Condition of Surfacing SOU				STU
c)	Riding Quality S/U				
d)	Road Camber S/U				
e)	aggregates in case of CC Pavement.				YesANo
(1)	Contraction Joints provided or not (CC Pavement) Yes/N				Yes/No N
g)	Compaction of flank/slope & raincuts if any Yes/No				Yes/No
2.	Cross Drainage N-A				NA
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U				
c)	Condition of railings/slab/approach for Bridges S/SRI/U				
3.	Road Furni	iture			
a)	Whether signature stones/Pave	gn boards/informato ment road markings a	ry/cautionary Board/km & are provided and maintained	200m	Yes/No
4.	Compliance	e History			
a)	Status of A	TR's & any others			No.

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SPET
Unsatisfactory (U)	U

Kisher Kumar NAME: A.E (Signature)