

FIELD INSPECTION REPORT

Date of Inspection : 17.12.2020	District: Muzaffarpur
Division : Muzaffarpur East-1	Length (km): 0.85 KM
Name of the Road: SOB Hira Harpur to Chhetaki Madhain	
Scheme/Programme: MAINTENANCE	GTSNY
Package No.:	Road Id No.: 31507218008
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls. Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

✓ Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

Bijendra Kumar

DESIGNATION:

JE / RWD (W)

Bandra

(Signature)
17.12.2020

AE

RWD (W)

Bandra