

FIELD INSPECTION REPORT

Date of Inspection : 20/12/2020	District: East Champaran
Division : Motihuri	Length (km): 1.077
Name of the Road: Suraspur PMGSY Road To Murchachak.	
Scheme/Programme: MAINTENANCE	
Package No.: BR/HR/598	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/K
b)	Condition of Surfacing	S/K
c)	Riding Quality	S/K
d)	Road Camber	S/K
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-S/SRI/U N.A
c)	Condition of railings/slab/approach for Bridges	-S/SRI/U N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained <i>Parapet Painting, 200m Post</i>	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others (Afreely submitted)	Pending

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

m/m
20/12/2020
(Signature)

NAME: Anil Kumar Prasad Thakur

DESIGNATION: J.E