

FIELD INSPECTION REPORT

Date of Inspection : 10/12/20		District: East Champaran	
Division : Motihari		Length (km): 1.266 km	
Name of the Road: Bhatla To Bhatla Laxwirda.			
Scheme/Programme: MAINTENANCE PMUSY			
Package No.:		Road Id No.: —	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1. Pavement			
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓	
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓	
2. Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRU/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRU/U NA	
c)	Condition of railings/slab/approach for Bridges	S/SRU/U NA	
3. Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓	
4. Compliance History			
a)	Status of ATR's & any others	NA	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	'U'

NAME: Rajendra Pr. Yadav
DESIGNATION: AE

12/12/20
J.E

(Signature) AE
12/12/20