

FIELD INSPECTION REPORT

Date of Inspection:	11-12-20	District:	East Champai
Division:	Arany	Length (km):	1.390 Km
Name of the Road:	Kanagar	Remarks:	to Kanagar RD satisfactorily
Scheme/Programme:	MAINTENANCE	Road Id No.:	
Package No.:			
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Construction/Rehabilitation/Maintenance		
Parameters to be checked		Remarks	
1. Pavement			
a) Road Junction condition			Yes
b) Condition of Surfacing			Yes
c) Riding Quality			Yes
d) Road Camber			Yes
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f) Contraction Joints provided or not (CC Pavement)			Yes/No
g) Compaction of flank/slope & raincuts if any			
2. Cross Drainage			
a) Condition of head walls in Hume pipe culverts including its painting			Yes/No
b) Condition of Abutment & Wing walls, Slab in RCC culverts			Yes/No
c) Condition of railings/slab/approach for Bridges			Yes/No
3. Road Furniture			
a) Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4. Compliance History			No
a) Status of ATR's & any others			

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

[Signature]
(Signature)



Shot on Y12

Vivo AI camera