

FIELD INSPECTION REPORT


Date of Inspection: 22/12/2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 3.211
Name of Road : TO-1 to Singhiya Panchim		
Scheme / Programme: MAINTENANCE		pmbsy
Package No: BR-30R-501		Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance

Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S
b)	Condition of Surfacing	R.I
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S
f)	Constraction Joint provided or not(CC Pavement)	-
g)	Compaction of flank/slope & raincuts if any	S
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridge	-
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	R.I
4	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

S.R.I

Satisfactory(S)	
✓ Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	


 22/12/2020
 (Signature)

NAME:
DESIGNATION :

Ramen Kumar Singh
 J.E