


# FIELD INSPECTION REPORT

Date of Inspection: 21.12.2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 4.127
Name of Road : MDR T03 to Mahamadpur		
Scheme / Programme: MAINTENANCE		pmbsy
Package No: BR-30R 513	Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance

Sl. No	Parameters to be Checked	Remarks
1	<b>Pavement</b>	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S
f)	Constraction Joint provided or not(CC Pavement)	S
g)	Compaction of flank/slope & raincuts if any	S
2	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridge	✓
3	<b>Road Furniture</b>	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S
4	<b>Compliance History</b>	
a)	Status of ATR's & any others	No

Overall Rating :

✓ Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	

  
 21.12.2020  
 (Signature)

Ramesh Kumar Sd.

NAME:  
DESIGNATION :

UE