


FIELD INSPECTION REPORT

Date of Inspection :	24-12-20	District:	Buxar
Division :	Buxar	Length (km):	0.585 km
Name of the Road:			
Scheme/Programme:	MAINTENANCE Gram Panchayat Panday Patti me Jag Nath		
Package No.:	Sah. Yashwantrao Wadgaonkar Yashwantrao		
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	☒ New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	W/U
b)	Condition of Surfacing	W/U
c)	Riding Quality	W/U
d)	Road Camber	W/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	S.R.I
Unsatisfactory (U)	


 (Signature) 24.12.20

NAME: