

Date of Inspection :	24/12/2020	District :	Nalamada
Division :	Rajgarh	Length (km) :	0.400 Km. (P.C.C.)
Name of the Road :	Lo 24 to Ravi Das to la		
Scheme/Programme :	MAINTENANCE		
Package No. :	Road Id No. :		
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & cutouts if any	Yes/No
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U
c)	Condition of railing/cut approach for Bridges	S/SR/U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4. Compliance History		
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SR)	S-R-2
Unsatisfactory (U)	

NAME: K. S. Prasad

DESIGNATION: Asst Engineer

24/12/2020
(Signature)