

FIELD INSPECTION REPORT

Date of Inspection : 21.12.2020		District: KISHANGANGJ
Division : KISHANGANGJ-2		Length (km): 0.700
Name of the Road: L039 NEAR SCHOOL TO GODRA		
Scheme/Programme: MAINTENANCE		GTSNY
Package No.:		Road Id No.: 21205901854
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U / S
b)	Condition of Surfacing	S/U / S
c)	Riding Quality	S/U / S
d)	Road Camber	S/U / S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U / ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NO
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: SUNIL KUMAR RANJAN
21.12.2020

(Signature)
22.12.2020