

FIELD INSPECTION REPORT

Date of Inspection : 21.12.2020	District: KISHANGANJ.
Division : KISHANGANJ-2	Length (km): 1.20
Name of the Road: L039 KAMARKHOD TO GUAWARI	
Scheme/Programme: MAINTENANCE	GTSNY.
Package No.:	Road Id No.: 8/205901862
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance


Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/V/S
b)	Condition of Surfacing	S/V/S
c)	Riding Quality	S/V/S
d)	Road Camber	S/V/S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NO
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI.
Unsatisfactory (U)	

NAME: SUNIL KR. RANJAN.

22.12.2020

(Signature) 
22.12.2020