FIELD INSPECTION REPORT

Date o	of Inspection: 26.	12.2020	District: Kishanganj	
	on: Kishanganj-1		Length/km):	
Name	of the Road: P	M 65 N TA	Rood To Ward 10 TO Bhatia	
Scheme/Programme: GTSNY			P 10 10 10 10 10 10 10 10 10 10 10 10 10	Tola
	ge No.:	0.0111		
Status of the Project:		Ongoing/Completed /Under Mainténance		6
Work is a case of:		New Connectivity/ Up gradation / Maintenance		
51. No		Paramete	vity/ Op gradation / Maintenance	
1.	Pavement	raramete	rs to be checked	Remarks
a)		Road Junction Condition		VS/U
b)				VS/U
c)	Condition of Surfacing Riding Quality			V S/U
d)	Road Camber			V S/U
				N S/U
e)	in case of CC Pa	rom defects suc avement.	ch as visible cracks, exposed aggregates	Yes/No
f)	Contraction Joints Provided or not (CC Pavement)			Yes/No
g)	Compaction of flank / shop & raincuts if any		Yes/No	
2.	Cross Drainage			V 163/110
a)	Condition of he	ead walls in Hum	ne pipe culverts including its Painting	S/SRI/U
b)	Condition of Al	butment & Wing	g walls, slab in RCC culverts	S/SRI/U
c)		ilings/Slab/appr		
3.	Road Furniture		VS/SRI/U	
a)	Whether sign b	Yes/No		
411	stones/Paveme	ent road marking	gs are provided and maintained	V 2007110
4.	Compliance His			
a)	Status of ATR's	& any others		

Overall Rating:

Satisfactory(S)	(5)	
Satisfactory but requires Improvement (SRI)		
Unsatisfactory(U)		

NAME: Umesh Kumar Singh J.E, RWD, Kishanganj

Scanned with CamScanner