## FIELD INSPECTION REPORT

		TILLD HAST LO.			
Date of Inspection: 26.12.2020			District: Kishanganj		
Division: Kishanganj-1			Length(km): 1.000 CM		
	f the Road:	PMGSY to	Banwari tola		
Scheme/Programme: GTSNY		,			
Package			Road Id No.: 21205801899	1	
Status of the Project:		Ongoing/Completed /Under Maintenance			
Work is a case of:		New Connectivity/ Up gradation / Maintenance		Remarks	
S1. No	Parameters to be checked				
1.	Deviament			<i>J</i> 8/U	
a)	Road Junction Condition			ر S/U	
b)	Condition of Surfacing			s/U	
	Riding Quality			s/U -	
c) d)	Road Camber			∕S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates			Yes/No	
۲,	in case of CC Pavement.				
f)	Contraction Joints Provided or not (CC Pavement)			X'es/No	
g)	Compaction of flank / shop & raincuts if any  Yes/			∕Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its Painting			&/SRI/U	
b)	Condition of Abutment & Wing walls, slab in RCC culverts			✓S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges  /S/SRI/L			∕S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m			Vés/No	
	stones/Pavem				
4.	Compliance History				
a)	Status of ATR's & any others				

## Overall Rating:

Satisfactory(S)	(3)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

(Signature)

NAME: Umesh Kumar Singh J.E, RWD, Kishanganj