FIELD INSPECTION REPORT

| Date | of Inspection : | 25/12/2020 | District: | - | | |
|--|--|---|--|------------|-----------|--|
| Length (km): | | | Patra 0.90 | | | |
| 1 | of the Road | SOR TO S | heetalgash | 0.70 | 2 | |
| Schen | ne/Programme. | MAINTENANCE | | | 1 | |
| Packa | ge No.: | Ongoing/Co. L. | Road Id No.: | | | |
| Status of the Project: Work is a case of: | | Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance | | | | |
| No. China | THE SHEET THE SHEET SHEET | | NOT THE OWNER OF THE OWNER OWN | N | | |
| SI. No. | | Parameters to be checked Remai | | | | |
| 1. | Pavement | | | | | |
| a) | Road Junction condition | | | | S s/U | |
| b) | Condition of Surfacing | | | | V S/U | |
| c) | Riding Quality | | | | S 8/U | |
| d) | Road Camber | | | | S S/U | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | | | | |
| f) | Contraction Joints provided or not (CC Pavement) | | | | Yes/No | |
| g) | Compaction of flank/slope & raincuts if any | | | | Ho Yes/No | |
| 2. | Cross Draina | ige | | | | |
| a) | Condition of head walls in Hume pipe culverts including its pa | | | inting | MAS/SRI/U | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culv | | alls, Slab in RCC culverts | HA S/SRI/U | | |
| c) | Condition of railings/slab/approach for Bridges | | HAS/SRI/U | | | |
| 3. | Road Furnitu | re | | | | |
| a) | Whether sign stones/Paveme | boards/informatory nt road markings ar | //cautionary Board/km & e provided and maintained | 200m | Yes/No | |
| 4. | Compliance H | listory | | | | |
|) | Status of ATR | s & any others | | | | |
| | | | | 100 | | |

Overall Rating

| Satisfactory (S) | |
|---|---|
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | U |

(Signature)

NAME: Dinesh choudhary