

# FIELD INSPECTION REPORT

Date of Inspection: 22.12.20		District: East Champaran
Location: Jhapa		Length (km): 1.43 km
Name of the Road: S.S. Kishanbhai Tola to S.S. Kishanbhai Tola (Ch. S.S. No. 1)		
Scheme/Programme: MAINTENANCE		Road Id No.:
Page No.:		
Name of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New/Connectivity/Up gradation/ Maintenance		
Parameters to be checked		
Sl. No.		Remarks
<b>1. Pavement</b>		
a)	Road Junction condition	Yes/No
b)	Condition of Surfacing	Yes/No
c)	Riding Quality	Yes/No
d)	Road Camber	Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
<b>2. Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting	Yes/No
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	Yes/No
c)	Condition of railings/slab/approach for Bridges	Yes/No
<b>3. Road Furniture</b>		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
<b>4. Compliance History</b>		
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)
Satisfactory but requires Improvement (SRI) SRI
Unsatisfactory (U)

Signature

NAME: Manish Kumar

DESIGNATION: J.E. R.W.D. Aram