

FIELD INSPECTION REPORT

Date of Inspection : 10/12/20		District: East Champaran
Division : Mithan		Length (km): 1.500 Km
Name of the Road: H/O Bivla Manthi To 1027		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRU/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRU/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRU/U NA
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4. Compliance History		
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	'SRI'
Unsatisfactory (U)	

NAME:

Paikendra Prasad

12/12/20
S.E.

(Signature)

Paikendra
12/12/20

DESIGNATION: A.C.