

FIELD INSPECTION REPORT

Date of Inspection : 12/12/2020	District: East Champaran
Division : Pakhidal	Length (km): 1.008 km
Name of the Road: Dhodhna Tola To RCO Salempur Road	
Scheme/Programme: MAINTENANCE	GTSWY
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
	Compliance History	
a)	Status of ATR's & any others	N-A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SR7
Unsatisfactory (U)	

Saleh
13/12/20
S-E

[Signature]
13/12/20
A-E
(Signature)