

FIELD INSPECTION REPORT

Date of Inspection : 19/12/2020		District: East Champaran	
Division : Pakhridaya		Length (km): 0.700 km	
Name of the Road: Sonaul Sahu Tola To mm GSY Road			
Scheme/Programme: MAINTENANCE		C.T.S.N.Y	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing		✓ S/U
c)	Riding Quality		✓ S/U
d)	Road Camber		✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓ S/U
f)	Contraction Joints provided or not (CC Pavement)		✓ Yes/No
g)	Compaction of flank/slope & raincuts if any		✓ Yes/No
2.	Clear Drainage		✓ Yes/No
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		S/SRI/U
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		✓ Yes/No
Compliance History			
a)	Status of ATR's & any others		N.A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	S
Unsatisfactory (U)	

Note - Flood damage reported

Satla
20/12/20
S.E

20.12.20
(Signature)