

FIELD INSPECTION REPORT

Date of Inspection : 18.12.2020
 Division : Rajgarh
 District : Nalgonda
 Name of the Road : T-5 to Chappal (km)
 Length (km): 0.556 km
 Scheme/Programme : MAUT-FINANCIAL
 Package No. :
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of RCC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank, slope & raincuts if any	Yes/No N/A
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRUU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRUU
c)	Condition of railings/slab/approach for Bridges	S/SRUU
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stores/Pavement markings are provided and maintained	Yes/No
4. Compliance History		
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	Satisfactory
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: K. Ramesh Prasad

DESIGNATION: Asst. Engineer

(Signature) 18.12.2020