

# FIELD INSPECTION REPORT

|                                                              |                                            |                    |
|--------------------------------------------------------------|--------------------------------------------|--------------------|
| Date of Inspection : 21/12/20                                |                                            | District: Araria   |
| Division : Forbessganj                                       |                                            | Length (km): 1.750 |
| Name of the Road: Ashu K Singh house to Baidnath Yadav house |                                            |                    |
| Scheme/Programme:                                            | MAINTENANCE ✓                              |                    |
| Package No.:                                                 | Road Id No.:                               |                    |
| Status of the Project:                                       | Ongoing/Completed/Under Maintenance ✓      |                    |
| Work is a case of:                                           | New Connectivity/Up gradation/ Maintenance |                    |

| Sl. No. | Parameters to be checked                                                                                             | Remarks   |
|---------|----------------------------------------------------------------------------------------------------------------------|-----------|
| 1.      | Pavement                                                                                                             |           |
| a)      | Road Junction condition                                                                                              | S/U       |
| b)      | Condition of Surfacing                                                                                               | S/U       |
| c)      | Riding Quality                                                                                                       | S/U       |
| d)      | Road Camber                                                                                                          | S/U       |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No ✓  |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | ✓ Yes/No  |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | ✓ Yes/No  |
| 2.      | Cross Drainage                                                                                                       |           |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓ S/SRI/U |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U   |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U   |
| 3.      | Road Furniture                                                                                                       |           |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No ✓  |
| 4.      | Compliance History                                                                                                   |           |
| a)      | Status of ATR's & any others                                                                                         |           |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            |   |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          | U |

*(Signature)*  
21/12/20

NAME: