

FIELD INSPECTION REPORT

Date of Inspection: 18.12.2020	District: Kishanganj
Division: Kishanganj-1	Length(km): 0.350 km
Name of the Road: Babhanga to 2.34.	
Scheme/Programme: GTSNY	
Package No.:	Road Id No.: 21205801816
Status of the Project:	Ongoing/Completed /Under Maintenance
Work is a case of:	New Connectivity/ Up gradation / Maintenance

S1. No	Parameters to be checked	Remarks
1.	Pavement	✓ S/U
a)	Road Junction Condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints Provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank / shop & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

P. Ravind
18-12-2020
(Signature)

NAME: Pravind Ravidas
J.E, RWD, Kochadhaman