

FIELD INSPECTION REPORT *BTSNy*

Date of Inspection :	24.12.2023	District:	Nalanda
Division :		Length (km):	1.80 Km (P.C.)
Name of the Road:	Loh to Lakshmi Bigha		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U <i>N/A</i>
b)	Condition of Surfacing	S/U <i>N/A</i>
c)	Riding Quality	S/U <i>N/A</i>
d)	Road Camber	S/U <i>N/A</i>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of Bank slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railing/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	<i>Satisfactory</i>
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

BTSNy
(Signature) 24.12.2023

NAME: *Kranti Poudyal*
DESIGNATION: *Assistant Engineer*