

16

FIELD INSPECTION REPORT

Date of Inspection: 24/12/2020	District: Samastipur	
Division: RWD Dalsinghsarai	Length(km): 1.81 km	
Name of Road: To 3 to Kherwan Jala		
Scheme / Programme:	MAINTENANCE	
Package No:	MDB	
Road Id No:		
Status of the Project: Ongoing/Completed/Under Maintenance ✓		
Work is a case of: <input checked="" type="checkbox"/> New Connectivity/ <input type="checkbox"/> Up gradation/ <input type="checkbox"/> Maintenance		
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S
f)	Constraction Joint provided or not(CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	SPI
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridge	
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	SPI
4	Compliance History	
a)	Status of ATR's & any others	N.

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SPI
Unsatisfactory(U)	

24/12/2020
(Sign: arc)

NAME:

DESIGNATION :

Anil Prasad
JB