

INSPECTION REPORT

Date of Inspection: 23.12.2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 2.013 Km
Name of Road : L032 to Maykothi.		
Scheme / Programme: MAINTENANCE	NABARD 4515 Acap.	
Package No:	Road Id No:	
Status of the Project: ☒ Ongoing/ ☐ Completed/ ☐ Under Maintenance		
Work is a case of:	☒ New Connectivity/ ☐ Up gradation/ ☐ Maintenance	

Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S
e)	Constraction Joint provided or not(CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
2	Cross Drainage	
	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridge	S
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	S.
Unsatisfactory(U)	

NAME: **Bem chandra Gupta**
 DESIGNATION: **Asst Engineer**
Morwa.

(Signature)
23/12/20