

FIELD INSPECTION REPORT GTSNY

Date of Inspection : 24.12.20		District: Buxar
Division : Buxar		Length (km): 1.00 km
Name of the Road: Jamarli Daitra Baba Kaulachoj Road to Parbat chak		
Scheme/Programme: MAINTENANCE		GTSNY
Package No.:		
Status of the Project: Ongoing/Completed/Under Maintenance		Under maintenance
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/P
c)	Condition of railings/slab/approach for Bridges	N/P
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	No
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SR2
Unsatisfactory (U)	

NAME: N.K. Himanshu

DESIGNATION:

सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल, राजपुर

24
25.12.20
(Signature)

अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल, राजपुर