

FIELD INSPECTION REPORT

Date of Inspection : 20-12-2020 District: Muzaffarpur
 Division : Muzaffarpur East-1 Length (km): 1.617 KM
 Name of the Road: Madhuban MMGSY (Brahmasthan) to Dharmuha
 Scheme/Programme: MAINTENANCE MMGSY (Gen)
 Package No.: Road Id No.: 31507201276
 Status of the Project: Ongoing Completed Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank-slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory-cautionary Board-km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N.A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

Brijendra Kumar

DESIGNATION:

JE / RWD (W)
Kurhani

K. Anilish
20/12/20

(Signature)

AE

RWD (W)

Kurhani