


## FIELD INSPECTION REPORT

|                                                          |  |                                            |
|----------------------------------------------------------|--|--------------------------------------------|
| Date of Inspection : 25.12.20                            |  | District: PATNA                            |
| Division : MASAU RH                                      |  | Length (km): 1.10                          |
| Name of the Road: BARIBIGHA DATMAI PATH TO BAZIDPUR ROAD |  |                                            |
| Scheme/Programme: MAINTENANCE                            |  |                                            |
| Package No.:                                             |  | Road Id No.:                               |
| Status of the Project:                                   |  | Ongoing/Completed/Under Maintenance        |
| Work is a case of:                                       |  | New Connectivity/Up gradation/ Maintenance |

| Sl. No. | Parameters to be checked                                                                                             | Remarks       |
|---------|----------------------------------------------------------------------------------------------------------------------|---------------|
| 1.      | Pavement                                                                                                             |               |
| a)      | Road Junction condition                                                                                              | ✓ S/U         |
| b)      | Condition of Surfacing                                                                                               | ✓ S/U         |
| c)      | Riding Quality                                                                                                       | ✓ S/U         |
| d)      | Road Camber                                                                                                          | S/U           |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No ✓      |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | ✓ Yes/No      |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No ✓      |
| 2.      | Gross Drainage                                                                                                       |               |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓ S/SRI/U     |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U ✓ N/A |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U ✓ N/A |
| 3.      | Road Furniture                                                                                                       |               |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No      |
| 4.      | Compliance History                                                                                                   |               |
| a)      | Status of ATR's & any others                                                                                         | —             |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) | — |
| Unsatisfactory (U)                          | — |

  
 25/12/20

(Signature)

NAME:

Chhoti Prasad

DESIGNATION: J.E. Work. Sub. Div. Dhananagar