

FIELD INSPECTION REPORT

Date of Inspection: 22-12-2017
 Location: # 1001-A
 Name of the Road: Muziyha + Laha
 Scheme/Programme: MAINTENANCE
 Package No.:
 Name of the Project: Highway Construction
 Work is a part of: New/Existing/Extension/Improvement

Parameters to be checked		Remarks
1	Pavement	
a)	Road Junction condition	OK
b)	Condition of Surfacing	OK
c)	Existing Quotry	OK
d)	Road Camber	OK
e)	Whether there have been defects such as surface cracks, exposed aggregates in case of CX Pavement	OK/No
f)	Construction Joints provided or not (CX Pavement)	Yes/No
g)	Compaction of Backfill & reinstatement	Yes/No
2	Cross Drainage	
a)	Condition of head walls in House pipe culverts including its opening	OK/No
b)	Condition of Abutment & Wing walls for RCC culverts	OK/No
c)	Condition of wing walls/abapproach for bridges	OK/No
3	Road Furniture	
a)	Whether sign boards/informances/existence of Road Lane or other road markings are provided and maintained	Yes/No
4	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating

Satisfactory (S)

Satisfactory but requires improvement (SRI)

Unsatisfactory (U)

5

(Signature)

NAME: Manish Kumar

DESIGNATION: JE RWD Group