

MMGSY(GEN)

**FIELD INSPECTION REPORT**

|                                                               |                       |
|---------------------------------------------------------------|-----------------------|
| Date of Inspection : 24.12.2020                               | District: Gorakhpur   |
| Division : Hathua                                             | Length (km): 0.485 km |
| Name of the Road: Madhya Vidhalaya Kandhgori To Dhobi Tola    |                       |
| Scheme/Programme: MAINTENANCE                                 |                       |
| Package No.:                                                  | Road Id No.:          |
| Status of the Project: Ongoing/Completed/Under Maintenance    |                       |
| Work is a case of: New Connectivity/Up gradation/ Maintenance |                       |

| Sl. No. | Parameters to be checked                                                                                             | Remarks     |
|---------|----------------------------------------------------------------------------------------------------------------------|-------------|
| 1.      | <b>Pavement</b>                                                                                                      |             |
| a)      | Road Junction condition                                                                                              | S/U (S)     |
| b)      | Condition of Surfacing                                                                                               | S/U (S)     |
| c)      | Riding Quality                                                                                                       | S/U (S)     |
| d)      | Road Camber                                                                                                          | S/U (S)     |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No NO   |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No NO   |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No Yes  |
| 2.      | <b>Cross Drainage</b>                                                                                                |             |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U N/A |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U N/A |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U N/A |
| 3.      | <b>Road Furniture</b>                                                                                                |             |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No Yes  |
| 4.      | <b>Compliance History</b>                                                                                            |             |
| a)      | Status of ATR's & any others                                                                                         | Yes         |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            |     |
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory (U)                          | U   |

Sheoshankar Paswan  
(Signature) 24.12.2020  
J.E

NAME: sheoshankar paswan  
DESIGNATION: J.E