

17

FIELD INSPECTION REPORT

| Date of Inspection: 24.12.2020 | District: Samastipur | |
|--|--|---------|
| Division: RWD Dalsinghsarai | Length(km): 0.340/km | |
| Name of Road: Lo 38 to Brahman Tola Manika Bishanpur | | |
| Scheme / Programme: MAINTENANCE | | |
| Package No: mmcsy | Road Id No: | |
| Status of the Project: Ongoing/Completed/Under Maintenance ✓ | | |
| Work is a case of: <input checked="" type="checkbox"/> New Connectivity/ <input type="checkbox"/> Up gradation/ <input type="checkbox"/> Maintenance | | |
| Sl. No | Parameters to be Checked | Remarks |
| 1 | Pavement | |
| a) | Road Junction Condition | S |
| b) | Condition of Surfacing | S |
| c) | Riding Quality | S |
| d) | Road Camber | S |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement | S |
| f) | Constraction Joint provided or not(CC Pavement) | |
| g) | Compaction of flank/slope & raincuts if any | S |
| 2 | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | M.A |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | |
| c) | Condition of railings/slab/approach for Bridge | |
| 3 | Road Furniture | |
| a) | Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | S |
| 4 | Compliance History | |
| a) | Status of ATR's & any others | N |

Overall Rating :

| | |
|--|---|
| Satisfactory(S) | S |
| Satisfactory but requires Improvement(SRI) | |
| Unsatisfactory(U) | |

24/12/2020
(Signature)

NAME:

DESIGNATION:

Anil Kumar

JB