## FIELD INSPECTION REPORT

	TIDED WILL	
Date of Inspection : 2	3.12.2020	District: W. Clambaran
Division: Belliah		Length (km): 1.50 2.7
Name of the Road: L	1 W- 8 H 8-1 #	Sout folis Syraki folis
Scheme/Programme:	MAINTENANC	17
Package No.:		Road Id No.: 31808800206
Status of the Project:	Ongoing/Comple	eted/Under Maintenance
Work is a case of:	New Connectivit	ty/Up gradation/ Maintenance
SI No.	Parameters	s to be checked Remarks

Work is	a case of:	New Connectivity/Up gradation/ Maintenance	THE RESERVE TO SERVE THE PERSON NAMED IN	a programmati in the control
Sl. No.		Parameters to be checked		Remarks
1.	Pavement	e la directa de la la la disposición de la la companya de la companya del companya de la companya de la companya del companya de la companya de la companya de la companya de la companya del companya de la companya del companya del companya de la companya de la companya de la companya del		and the second second
a)	Road Junction	Road Junction condition		S/U-
b)	Condition of Surfacing U		S/U	
c)	Riding Quality \$		∟S/U	
d)	Road Camber &		Ŀ\$/U	
e)	Whether fr	ree from defects such as visible cracks, en case of CC Pavement.	exposed N Q	Yes/No
f)		Joints provided or not (CC Pavement)	Life	Yes/No
g)		of flank/slope & raincuts if any	HO	Yes/No
2.	Cross Drai	nage		
a)	Condition o	of head walls in Hume pipe culverts including its	painting	✓S/SRI/U
b)		of Abutment & Wing walls, Slab in RCC culverts		✓S/SRI/U
c)		f railings/slab/approach for Bridges	NIA	S/SRI/U
3.	Road Furn		da.	The section of
a)	Whether si	ign boards/informatory/cautionary Board/km ement road markings are provided and maintaine	& 200m	Yes/No
4.	Compliano	se History	NAME OF THE RES	a same same and
a)	Status of A	TR's & any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	1
Unsatisfactory (U)	10

(Signature)

NAME: JUNEL BUHAR

DESIGNATION: J.E