

Status of the Project:		Ongoing/Completed/Under Maintenance	complete
Work is a case of:		✓ New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition	✓	S/U
b)	Condition of Surfacing	✓	S/U
c)	Riding Quality	✓	S/U
d)	Road Camber	✓	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓	Yes/No
g)	Compaction of flank/slope & raincuts if any	✓	Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	NA	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA	S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓	Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	X

Anurag
23-12-2020
(Signature)

TH
RWD Rajpur

nsari
ME: