

# FIELD INSPECTION REPORT

|                        |                                                         |              |          |
|------------------------|---------------------------------------------------------|--------------|----------|
| Date of Inspection :   | 22-12-2020                                              | District:    | Buxar    |
| Division :             | Buxar                                                   | Length (km): | 1.526 Km |
| Name of the Road:      | Dhangoi - Kakasia road to Deekuli Kote highway Khenkhat |              |          |
| Scheme/Programme:      | MAINTENANCE MCHS (SC)                                   |              |          |
| Package No.:           |                                                         | Road Id No.: |          |
| Status of the Project: | Ongoing/Completed/Under Maintenance <u>Completed</u>    |              |          |
| Work is a case of:     | <u>New Connectivity/Up gradation/ Maintenance</u>       |              |          |

| Sl. No. | Parameters to be checked                                                                                        | Remarks       |
|---------|-----------------------------------------------------------------------------------------------------------------|---------------|
| 1.      | <b>Pavement</b>                                                                                                 |               |
| a)      | Road Junction condition                                                                                         | ✓ S/U         |
| b)      | Condition of Surfacing                                                                                          | ✓ S/U         |
| c)      | Riding Quality                                                                                                  | ✓ S/U         |
| d)      | Road Camber                                                                                                     | ✓ S/U         |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                    | ✓ Yes/No      |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                | NA Yes/No     |
| g)      | Compaction of flank/slope & raincuts if any                                                                     | NA Yes/No     |
| 2.      | <b>Cross Drainage</b>                                                                                           |               |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                            | ✓ S/SRI/U     |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                        | NA S/SRI/U    |
| c)      | Condition of railings/slab/approach for Bridges                                                                 | NA S/SRI/U    |
| 3.      | <b>Road Furniture</b>                                                                                           |               |
| a)      | Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained | 200m ✓ Yes/No |
| 4.      | <b>Compliance History</b>                                                                                       |               |
| a)      | Status of ATR's & any others                                                                                    | No            |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) | X |
| Unsatisfactory (U)                          | X |

Mubarak Hussain Ansari

NAME:

*Mubarak Hussain Ansari*  
22-12-2020  
(Signature)

R.W.D. Raipura