

# FIELD INSPECTION REPORT

|                        |                                            |              |          |
|------------------------|--------------------------------------------|--------------|----------|
| Date of Inspection :   | 24-12-2020                                 | District:    | Buxar    |
| Division :             | Buxar                                      | Length (km): | 1.300 Km |
| Name of the Road:      | Buxar - Dinara road to SIKOH BARKHIA       |              |          |
| Scheme/Programme:      | MAINTENANCE CTSNY                          |              |          |
| Package No.:           |                                            | Road Id No.: |          |
| Status of the Project: | Ongoing/Completed/Under Maintenance ✓      |              |          |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance |              |          |


| Sl. No. | Parameters to be checked                                                                                        | Remarks       |
|---------|-----------------------------------------------------------------------------------------------------------------|---------------|
| 1.      | Pavement                                                                                                        |               |
| a)      | Road Junction condition                                                                                         | ✓ S/U         |
| b)      | Condition of Surfacing                                                                                          | ✓ S/U         |
| c)      | Riding Quality                                                                                                  | ✓ S/U         |
| d)      | Road Camber                                                                                                     | ✓ S/U         |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                    | ✓ Yes/No      |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                | ✓ Yes/No      |
| g)      | Compaction of flank/slope & raincuts if any                                                                     | Yes/No ✓      |
| 2.      | Cross Drainage                                                                                                  |               |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                            | ✓ S/SRI/U     |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                        | NO ✓ S/SRI/U  |
| c)      | Condition of railings/slab/approach for Bridges                                                                 | NO ✓ S/SRI/U  |
| 3.      | Road Furniture                                                                                                  |               |
| a)      | Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained | 200m ✓ Yes/No |
| 4.      | Compliance History                                                                                              |               |
| a)      | Status of ATR's & any others                                                                                    |               |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) | X |
| Unsatisfactory (U)                          | X |

M.H. Ansari

NAME:

  
 24-12-2020  
 (Signature)

R.W.D. Raipura