

FIELD INSPECTION REPORT

Date of Inspection : 22-12-2020		District: Buxar
Division : RWD, DUMRAON		Length (km): 1.3 km
Name of the Road: Buxar Kailwar Bandh Se North-West Sima mahaxidera		
Scheme/Programme:	MAINTENANCE	MMGSY (GEN)
Package No.:	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	"
Satisfactory but requires Improvement (SRI)	"SRI"
Unsatisfactory (U)	

Road Signage required repainting

Akshay
22/12/2020
JE

V. K. Singh
22/12/2020
AE

(Signature)

NAME:

DESIGNATION: