FIELD INSPECTION REPORT

Data of Inspection :	22-12-2020	District: Saran/chapra		
		Length (km): 1.50 km.		
Division: chapte	7 - 1/1/102 C	mansu tola mahamada		
Name of the Road: 705. 4H 102 Se manger tola make made Scheme/Programme: MAINTENANCE (G. 75.K/Y.)				
Scheme/Programme:	MAINTENANCE	(4/3.47)		
Package No.:		Road Id No.: 3130 62 18002		
	Ongoing/Completed/Under Maintenance			
Status of the Project:	New Connectivity/Up gradation/ Maintenance			
Work is a case of:	New Connectivity of grand			

Sl. No.	Parameters to be checked	Remarks	
	The state of the s		
山村特	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
	Compaction of flank/slope & raincuts if any		
2.7	Cross Drainage	The Marie	
	Condition of head walls in Hume pipe culverts including its painting	S/SBA/U	
a)	Condition of Abutment & Wing walls, Slab in RCC culverts		
b)	Condition of railings/slab/approach for Bridges		
c)	· · · · · · · · · · · · · · · · · · ·		
3.	Trong I w	¥€s/No	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	621
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

NAME: Chemebravor Narayan DESIGNATION: T-A(Ex. Ex)