

FIELD INSPECTION REPORT

Date of Inspection : 25.11.2020		District: U. Champaran
Division : Narkatagang		Length (km): 8.300km
Name of the Road: S.K.G. to Bhabarpur		
Scheme/Programme: MAINTENANCE		
Package No.: Old MP 305Y		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
f)	Contraction Joints provided or not (CC Pavement)	—
g)	Compaction of tank/slope & rain cuts if any	—
2.	Cross Drainage	
a)	Condition of bend walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary board/km & 200m stones/Pavement road markings are provided and maintained	S
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—


 25/12/20
 (Signature)

NAME: Chandradeo Pd
 DESIGNATION: JE