

FIELD INSPECTION REPORT

Date of Inspection :	23.12.2020	District :	Jamui
Division :	Jamui	Length (Km) :	7.35 KM
Name of the Road :	Borhat Tamkuliya Bhaluka to Kundas border road		
Scheme/Programme :	MAINTENANCE MR(3054)		
Package No. :		Road Id No. :	20804108179
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	Pots filled up with metal
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	} NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	Yes/No	KMB 200 M Missing
4	Compliance History		
a)	Status of ATR's & any others	NA	

Overall Rating :

Satisfactory (S)	/
Satisfactory but requires Improvement (SRI)	/
Unsatisfactory (U)	U

NAME : RATIV RANJAN KUMAR
DESIGNATION : EE

Ratib Ranjan Kumar
(Signature)