

FIELD INSPECTION REPORT

Date of Inspection :	23.12.2020	District :	Jamui
Division :	Jamui	Length (Km) :	6.8 KM
Name of the Road :	Malaypur Barhat Phulwaria to Barhat Anjan Dam road.		
Scheme/Programme :	MAINTENANCE MR(3054)		
Package No. :		Road Id No. :	20804100839
Status of the Project :	Ongoing/Completed/Under Maintenance ☒		
Work is a case of :	New Connectivity/Up gradation/Maintenance ☒		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	☒ S/U	
b)	Condition of Surfacing	☒ S/U	6 upto 3 km
c)	Riding Quality	☒ S/U	Beyond 3 km due to camo work ongoing
d)	Road Camber	☒ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	☒ Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	☒ S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	Yes/No ☒	Sign board 200m missing beyond 3.0 km not maintained.
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	/
Unsatisfactory (U)	✓

NAME : RASIVRANJAN KUMAR
DESIGNATION : EE

R Kumar
23/12/2020
(Signature)