

# FIELD INSPECTION REPORT

|                         |                                                                                                                      |                   |                                            |
|-------------------------|----------------------------------------------------------------------------------------------------------------------|-------------------|--------------------------------------------|
| Date of Inspection :    | 23.12.2020                                                                                                           | District :        | Jamui                                      |
| Division :              | Jhajha                                                                                                               | Length (Km) :     | 5.0 KM                                     |
| Name of the Road :      | Sono Main road Kendua More to High school<br>Kuhik More Via Kowali Kauchampur Road.                                  |                   |                                            |
| Scheme/Programme :      | MAINTENANCE MR(3054)                                                                                                 |                   |                                            |
| Package No. :           |                                                                                                                      | Road Id No. :     | 20804200841                                |
| Status of the Project : | Ongoing/Completed/Under Maintenance                                                                                  |                   |                                            |
| Work is a case of :     | New Connectivity/Up gradation/Maintenance                                                                            |                   |                                            |
| Sl. No.                 | Parameters to be checked                                                                                             | Remarks           |                                            |
| 1                       | <b>Pavement</b>                                                                                                      |                   |                                            |
| a)                      | Road Junction condition                                                                                              | ✓S/U              |                                            |
| b)                      | Condition of Surfacing                                                                                               | S/U               | Pets filled up with metal at school place. |
| c)                      | Riding Quality                                                                                                       | ✓S/U              |                                            |
| d)                      | Road Camber                                                                                                          | ✓S/U              |                                            |
| e)                      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No            | } NA                                       |
| f)                      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No            |                                            |
| g)                      | Compaction of flank/slope & raincuts if any                                                                          | ✓Yes/No           |                                            |
| 2                       | <b>Cross Drainage</b>                                                                                                |                   |                                            |
| a)                      | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓S/SRI/U          |                                            |
| b)                      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U           | } NA                                       |
| c)                      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U           |                                            |
| 3                       | <b>Road Furniture</b>                                                                                                |                   |                                            |
| a)                      | Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained | Yes/No            |                                            |
| 4                       | <b>Compliance History</b>                                                                                            |                   |                                            |
| a)                      | Status of ATR's & any others                                                                                         | ATR not regraded. |                                            |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | / |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          | U |

NAME : RAJIV RANJAN KUMAR  
DESIGNATION : EE

*Rajiv Ranjan Kumar*  
(Signature) 23/12/2020