

FIELD INSPECTION REPORT

in A.R. Ward

Date of Inspection : 22.12.2020
 Division : Muzaffarpur District : Muzaffarpur
 Name of the Road : H-102 Street, Cantonment, Muzaffarpur Length (km): 1.5
 Scheme/Programme : MAINTENANCE Road Id No.: 3150 741 2027
 Package No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	S S/U
c)	Riding Quality	U S/U
d)	Road Camber	U S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S S/U
f)	Contraction Joints provided or not (CC Pavement)	Rough - Yes/No
g)	Compaction of flank/slope & raincuts if any	S Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Revised Painting Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

20/12/2020
 (Signature)

NAME: Debananda Nath

DESIGNATION: AE