

FIELD INSPECTION REPORT

Date of Inspection :	22.12.2020	District:	Muzaffargarh
Division :	Muzaffargarh West	Length (km):	
Name of the Road:	K.R. 59 Middle Island Bontapur P.S. East Tola Ph. Station		
Scheme/Programme:	MAINTENANCE	Km 1/2 to 1/4	
Package No.:		Road Id No.:	31507412040
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	SR/S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S Yes/No
f)	Contraction Joints provided or not (CC Pavement)	S Yes/No
g)	Compaction of flank/slope & raincuts if any	Remains Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	Painted S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Painting Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SR/
Unsatisfactory (U)	

22/12/2020
(Signature)

NAME: Derendra Hathi

DESIGNATION: AE