

FIELD INSPECTION REPORT

Date of Inspection: 22-12-2020		District: Muzaffarpur
Division: Muzaffarpur West		Length (km):
Name of the Road: Panda bazar to Jha Keshar Khatu to Prasadpur		
Scheme/Programme: MAINTENANCE		Package No.: 176054 (2019)
Status of the Project: Ongoing/Completed/Under Maintenance		Road Id No.: 315274/2084
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	SR/ S/U
c)	Riding Quality	SR/ S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Rough Yes/No
f)	Contraction Joints provided or not (CC Pavement)	S Yes/No
g)	Compaction of flank/slope & raincuts if any	Raincuts Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SR/ S/ SR/ U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S S/ SR/ U
c)	Condition of railings/slab/approach for Bridges	S S/ SR/ U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Painting Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Date: 22/12/2020
(Signature)

NAME: Devidas Haldar

DESIGNATION: AE